



M0190005
Task ID# 7484
Rec'd 7/5/2016
cc: Mike

Application for Bond Release

Operator/Permittee: Intrepid Potash - Moab LLC	
Mine/Project Name: Cane Creek Mine	Permit ID#: M/019/0005
	Permitted Acres:
Reason for Bond Release: Structures removed	
Amount of Existing Surety: \$5,232,000	
Amount of Surety requested for release: \$8,000	
Partial Release of a <u>portion</u> * of the mine site: Acres Regraded: 1 Specify Area: Facilities Area	Partial Release of <u>entire</u> mine site: (Backfilling and grading are completed) Acres:
Full Release of a <u>portion</u> * of the mine site: Acres to be released: Specify Area:	Full Release of <u>entire</u> mine site: (Vegetation is established and has survived three growing seasons.) Acres to be released:
*For a bond release on a portion of the mine site, submit an updated map removing the released area from the disturbed or bonded area.	



Application for Bond Release

Reclamation practices must be completed in accordance with R647-2-109, or R647-3-109, or R647-4-111 as applicable.

Have any shafts and tunnels been permanently sealed?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Disposal of debris & other materials incident to mining	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Public safety notifications such as posted signs or fences/barriers above high walls	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Drainages, reestablished & stable	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Structures demolished and deleterious materials disposed of	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Erosion Controlled	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Slopes, waste piles, fills regraded	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Highwalls stabilized to an angle of 45° or less	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Meets Post mining Land Use (Indicate Land use)	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Roads and/or pads have been reclaimed	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Dams, Impoundments, Ditches, Pits reclaimed	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Topsoil redistributed – amendments added	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Vegetation meets 70% of the pre-mining cover?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
<p><i>Note: For Final Bond Release vegetation must meets 70% of premining cover and has survived three years for or has survived one year growing season to maintain small mine status.</i></p>	
Plugging of boreholes	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
<p>If Answer is Yes, please fill out page 3 of this form</p>	
<p>DESCRIPTION of RECLAMATION ACTIVITIES COMPLETED (Describe any variance(s) that have been granted, date activity completed)</p> <p>Structures removed from the mine facilities area are as follows: 1 Feed Receiving Tank, Tailing Thickener, Cooling Tower, Sewage Treatment Plant, Tanks West of Thickener, and Two Furnaces on side of Crystallizer Building.</p>	



I hereby certify that I am a responsible official of the applicant and that the information contained in this application is true and correct to the best of my information and belief in all respects with the laws of Utah in reference to commitments and obligations, herein.